

STRENGTHS.

1. DEVELOPMENT TO THE STATE/COUNTRY.
2. CONNECTIVITY
3. COMMUNICATION [FASTER & CHEAPER MODE].
4. ASSET TO THE STATE & THE COUNTRY.

WEAKNESS.

1. RAILWAY ROUTE PASSES THROUGH THE PA.
2. DESTRUCTION OF THE NATURAL HABITAT & OTHER RESOURCES.
3. LOSS OF LIFE.

OPPORTUNITIES.

1. OUT OF THE 5 COMPARTMENTS IN THE SANCTUARY ONLY C-1 & A PART OF C-2 IS AFFECTED.

SOLUTIONS.

- * SPEED REDUCTION IS MANDATORY
- * PROPER MONITORING AND TRAINING OF DRIVERS WITH REGARDS TO THE STRETCH (10-15KM) WITHIN THE PA
- * CONTROL ROOM STAFF & DRIVERS SHOULD BE FULLY DEDICATED WITH RESPECT TO ANIMAL LIFE.
- * WATCH TOWER TO BE CONSTRUCTED AT FEW POINTS WITHIN THE STRETCH OF THE RAILWAY LINE (INSIDE PA).
- * REGULAR MAINTENANCE OF TRAINS/TRACKS TO AVOID ANY UNTOWARD INCIDENCE.
- * HI-TECH/SENSORS IN THE RAILWAY TRACK/TRAIN TO DETECT THE ANIMALS/HUMANS PASSES THE PATH.
- *** AWARENESS PROGRAMS

PRESENTED BY,
RAILWAYS

STRENGTHS.

1. DEVELOPMENT TO THE STATE/COUNTRY.
2. CONNECTIVITY
3. COMMUNICATION [FASTER & CHEAPER MODE].
4. ASSET TO THE STATE & THE COUNTRY.

WEAKNESS.

1. RAILWAY ROUTE PASSES THROUGH THE PA.
2. DESTRUCTION OF THE NATURAL HABITAT & OTHER RESOURCES.
3. LOSS OF LIFE.

OPPORTUNITIES.

1. OUT OF THE 5 COMPARTMENTS IN THE SANCTUARY ONLY C-1 & A PART OF C-2 IS AFFECTED.

SOLUTIONS.

- * SPEED REDUCTION IS MANDATORY
- * PROPER MONITORING AND TRAINING OF DRIVERS WITH REGARDS TO THE STRETCH (10-15km) WITHIN THE PA
- * CONTROL ROOM STAFF & DRIVERS SHOULD BE FULLY DEDICATED WITH RESPECT TO ANIMAL LIFE.
- * WATCH TOWER TO BE CONSTRUCTED AT FEW POINTS WITHIN THE STRETCH OF THE RAILWAY LINE (INSIDE PA)
- * REGULAR MAINTENANCE OF TRAINS/TRACKS TO AVOID ANY UNTOWARD INCIDENCE.
- * HI-TECH/SENSORS IN THE RAILWAY TRACK/TRAIN TO DETECT THE ANIMALS/HUMANS PASSES THE PATH.
- *** AWARENESS PROGRAMS

PRESENTED BY,
RAILWAYS
